




Technology Surveys & Inspections

Aerial Photogrammetry, Mapping & Photography, Asset Surveys, 3D modeling,
LIDAR Floor Plans

Inspection Report 6516 Canary St. Sarasota FL 34241

Shingle damage on the ridge vent in 2 locations. Photos below indicating position.





Technology Surveys & Inspections

Aerial Photogrammetry, Mapping & Photography, Asset Surveys, 3D modeling,
LIDAR Floor Plans

